

Figure 5. Correlation between EPM excitation, lost ions and stored energy: losses increase and stored energy saturates at the onset of the EPMs. Conditions as in figure 1, P_{rf} = 6.3 MW